## BACCHUS MARSH HERITAGE STUDY.

Richard Peterson Architect & Conservation Consultant. Daniel Catrice Historian 1994.

NAME: ---

ADDRESS: Lerderderg Gorge Road (North of Morven) Darley.

TITLE DETAILS:

USE: Farmhouse.

**CONSTRUCTION DATE:** 

1870s

**SOURCE:** Visual

DESIGNER: ?

BUILDER:

SOURCE: -

CRITERIA: H1; Ar1.

**HISTORIC THEME:** Agricutural

**DESCRIPTION:** 

STYLE: Early

STORIES: 1

DETACHED.

**MATERIALS:** 

ROOF Iron

STRUCTURE

CONDITION: Good?

WALLS Timber INTACTNESS: Good?

THREATS:

SIGNIFICANT INTACT ELEMENTS:

FORM. FACADE. VERANDAH.

VERANDAH DECORATION. CONTEXT: 363

SIGNIFICANCE:


TYPE: HISTORICAL. ARCHITECTURAL.

LEVEL: LOCAL.

**DESIGNATION EXISTING: Nil** 

RECOMMENDED CONTROL: PLANNING SCHEME.

MAP NO: R2.04 SURVEY: RP, GW & JS DATE: 11.4.94 NEGS: 30.15 & 16



HISTORY: No information available.

VISUAL DESCRIPTION: An L-shaped gable-roofed farmhouse, probably nineteenth century (and possible early). The right hand bay is set forward as a hip-roofed wing. The skillion verandah is in the angle. At left is an external chimney. The left-hand wing, across the site, is five bays and symmetrical, with two doors. All five visible windows are 12-paned double-hung sashes.

**COMPARATIVE ANALYSIS:** There are fifteen early farmhouses in Bacchus Marsh identified in the Study. This one appears to be comparable to refs: 307 and 360 in particular.

**SIGNIFICANCE:** A late nineteenth century relatively intact farmhouse complex located in a beautiful river valley setting.

It is locally significant historically as an embodiment of a way of life, its social values and an agricultural practice. It has local architectural significance as a representative early style farmhouse.

**INTACTNESS:** Probably good.

CONDITIONS & THREATS: Good.