RICHMOND CONSERVATION STUDY **BUILDING ADDRESS** Richmand Terrace 3 TYPE Penidence & Valiny. **BUILDING TITLE EXISTING DESIGNATION HBR** NER NTC C D EΓ **GRADING** STREETSCAPE 2 CONSERVATION AREA 1 3 SURVEY DATE 22/11/84 NEG. FILE 107 24 **PERIOD** Early Victorian Edwardian Victorian Late Victorian CONSTRUCTION DATE Source **MATERIALS** Walls Brick Roof low. Van. **FORM** Detached Attached SIGNIFICANT FEATURES eaves, roof or gable decoration early paint colour scheme intact verandah original unpainted decoration early fence wall detailing early original garden doors/windows other prominent intact verandah contrib, elevations structure (Pwt) original parapet original roof form & finish original chimneys fair **INTEGRITY RATING** excellent good poor **ALTERATIONS & SPECIFIC GUIDELINES** No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G. 4. V/ Structure R = remove RAM = Remove by approved method O = reinstate original designs S = reinstate sympathetic alternative COMMENTS

BUILDING IDENTIFICATION FORM