BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY
BUILDING ADDRESS 39 STANLEY ST
BUILDING TITLE 'BEULAH' TYPE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 31-7-84 NEG. FILE 36-22 PERIOD Early Victorian Edwardian Victorian
Late Victorian
CONSTRUCTION DATE Source
MATERIALS Walls CEMENT RENDER Roof
FORM Attached Detached Detached
significant Features early paint colour scheme gable decoration gable gable decoration gable decoration gable decoration gable decoration gable gab
INTEGRITY RATING excellent good fair poor
ALTERATIONS & SPECIFIC GUIDELINES No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G.
PAINTED RENDER RAM RECESSED ENTRANCE O
WINDOWS
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method
COMMENTS