

# CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

LORRAINE HUDDLE  
LOUISE HONMAN  
RICHARD AITKEN

211512

1986

BUILDING ADDRESS **11 Wellington Street**

Type **R** Original Use **R**

PRESENT BUILDING TITLE

EXISTING DESIGNATION & FILE No. HBR No.  NER No.  NTC FN.  GRC No.

GRADING A  B  C  D  E  S

STREETSCAPE LEVEL 1  2  3  CONSERVATION AREA

SURVEY DATE **2-4-86**

NEG. FILE **017007 006**

PERIOD  
Early Victorian   
Victorian   
Late Victorian   
Edwardian   
Inter War   
Post War



MATERIALS  
walls **kin** roof **ca**

CONSTRUCTION DATE **1870s & 1910s** source

SIGNIFICANT FEATURES

original materials	<input checked="" type="checkbox"/>	early paint colour scheme or original unpainted finish	<input type="checkbox"/>	ornamental wall detailing	<input type="checkbox"/>
original doors, windows, hoods	<input checked="" type="checkbox"/>	intact verandah / porch structure	<input type="checkbox"/>	original parapet	<input type="checkbox"/>
original roof form and finish	<input type="checkbox"/>	original chimneys	<input type="checkbox"/>	eaves roof or gable decoration	<input type="checkbox"/>
intact verandah decoration	<input checked="" type="checkbox"/>	early fence	<input type="checkbox"/>	early garden	<input type="checkbox"/>
other prominent contributing elevations	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>

INTEGRITY RATING excellent  good  fair  poor

ALTERATIONS & SPECIFIC GUIDELINES						
No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
			<i>fence</i>	<i>s</i>		
			<i>cable wiring</i>	<i>-</i>		
			<i>ceiling vent</i>	<i>s</i>		

n : reinstate original design r : remove  
s : reinstate sympathetic alternative ram: remove by approved method