## RICHMOND CONSERVATION STUDY **BUILDING ADDRESS** 191 SWAN ST **TYPE** SHOP **BUILDING TITLE** If not residence **EXISTING DESIGNATION HBR NER** NTC В С D ЕΓ **GRADING** 2 CONSERVATION AREA STREETSCAPE 1 3 NEG. FILE 58-9 SURVEY DATE 12.7.84 **PERIOD** Edwardian Early Victorian Victorian Late Victorian **CONSTRUCTION DATE** Source **MATERIALS** Roof Walls BRICK **FORM** Detached Attached SIGNIFICANT FEATURES eaves, roof or early paint gable decoration colour scheme original unpainted intact verandah decoration wall finish early ornamental fence wall detailing early doors/windows FLOOR garden other prominent contrib, elevations intact verandah structure original SHOP FRONT TILE WORK parapet original roof form & finish original chimneys fair **INTEGRITY RATING** poor excellent good **ALTERATIONS & SPECIFIC GUIDELINES** S.G. S.G. S.G. Inappropriate Extremely Inappropriate No. Sympathetic SIGNAGE 5 S VERANDAH REMOVAL RAM = Remove by approved method S = reinstate sympathetic alternative R = remove O = reinstate original designs **COMMENTS**

**BUILDING IDENTIFICATION FORM**