

BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS 2 TENNYSON ST.

BUILDING TITLE GALE PTY. LTD.

TYPE

If not residence

FACTORY

EXISTING DESIGNATION

HBR ☐

NER ☐

NTC ☐

GRADING

A ☐

B ☐

C ☐

D ☒

E ☐

F ☐

STREETSCAPE

1 ☐

2 ☐

3 ☐

CONSERVATION AREA ☐

SURVEY DATE 1.12.84

NEG. FILE 120 - 19

PERIOD

Early Victorian ☐

Edwardian ☐

Victorian ☐

INTER ☒

Late Victorian ☐

CONSTRUCTION DATE

Source

MATERIALS

Walls BRICK

Roof

FORM

Attached ☐

Detached ☒

SIGNIFICANT FEATURES

early paint colour scheme ☐

eaves, roof or gable decoration ☐

original unpainted wall finish ☐

intact verandah decoration ☐

ornamental wall detailing ☐

early fence ☐

original doors/windows ☒

early garden ☐


intact verandah structure ☐

other prominent contrib. elevations ☐

original parapet ☒

original roof form & finish ☐

original chimneys ☐



INTEGRITY RATING

excellent ☐

good ☐

fair ☒

poor ☐

ALTERATIONS & SPECIFIC GUIDELINES

No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G.

PAINTED B'WK.

RAM

O = reinstate original designs

S = reinstate sympathetic alternative

R = remove

RAM = Remove by approved method

COMMENTS