BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY BUILDING ADDRESS 17 19 Wangavalla Gliveet TYPE **BUILDING TITLE** If not residence **HBR NER EXISTING DESIGNATION** NTC C **GRADING** В D E [F 2 STREETSCAPE 1 3 CONSERVATION AREA SURVEY DATE 21.11. 84 NEG. FILE 11-17 PERIOD Edwardian Early Victorian Victorian Late Victorian **CONSTRUCTION DATE** Source **MATERIALS** Walls byok Roof Cow. Van **FORM** Attached Detached SIGNIFICANT FEATURES eaves, roof or early paint gable decoration colour scheme intact verandah decoration(()) original unpainted wall finish ornamental fence (19) wall detailing early original garden doors/windows intact verandah structure (10) other prominent contrib. elevations(17). original original roof chimneys (19) INTEGRITY RATING excellent good fair poor **ALTERATIONS & SPECIFIC GUIDELINES** No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G. 4 V/9knouve 4 O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method **COMMENTS**