BUILDING IDENTIFICATION FORM
BUILDING ADDRESS 39 YORKSHIRE ST
BUILDING TITLE TYPE
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 28.6.84 NEG. FILE 20-28
PERIOD       Early Victorian       Victorian       Late Victorian
CONSTRUCTION DATE Source
MATERIALS Walls BRICK Roof IRON
FORM Attached Detached Detached
SIGNIFICANT FEATURES         early paint colour scheme       eaves, roof or gable decoration         original unpainted wall finish       intact verandah decoration         ornamental wall detailing       early fence         original doors/windows       early garden         intact verandah structure       early garden         original parapet       other prominent contrib, elevations         original parapet       PATH TILLING         original chimneys       intact verandah
INTEGRITY RATING excellent good fair poor
ALTERATIONS & SPECIFIC GUIDELINES         No.       Sympathetic       S.G.       Inappropriate       S.G.       Extremely Inappropriate       S.G.         Image: Imag
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method
COMMENTS