

# CARLTON CONSERVATION STUDY BUILDING IDENTIFICATION FORM

NIGEL LEWIS AND ASSOCIATES  
1984  
Nigel Lewis Richard Aitken

BUILDING ADDRESS 117 119 ARNOLD ST

BUILDING TITLE \_\_\_\_\_

TYPE  
IF NOT RESIDENCE

EXISTING DESIGNATION

HBR No \_\_\_\_\_

AHC \_\_\_\_\_

GRADING

A  B  C  D  E  F   
No \_\_\_\_\_

STREETSCAPE

1  2  3

CONSERVATION AREA

SURVEY DATE

16/2/84

NEG FILE

14/10

TITLE

VOL \_\_\_\_\_ FOL \_\_\_\_\_

STYLE

VICTORIAN

CONSTRUCTION DATE

SOURCE

MATERIALS

WHERE NOT APPARENT



NOTABLE FEATURES/SIGNIFICANCE

FENCE POSTS, C.I. FENCE + VERANDAH  
117

unpainted cement render  unpainted decorative brickwork  retains evidence of early colours or finishes  intact shop front  post supported shop verandah  elaborate/high standard design of cement rendered surfaces

INTEGRITY

EXCELLENT  GOOD  FAIR  POOR   
Nos 117 119

ALTERATIONS AND RECOMMENDATIONS

NOS SYMPATHETIC RECS INNAPPROPRIATE RECS EXTREMELY INNAPPROPRIATE RECS

NOS	SYMPATHETIC	RECS	INNAPPROPRIATE	RECS	EXTREMELY INNAPPROPRIATE	RECS
<u>119</u>					<u>SAND BLASTED BRK</u>	<u>?</u>

O = REINSTATE ORIGINAL DESIGN; S = REINSTATE SYMPATHETIC ALTERNATIVE; R = REMOVE; RAM = REMOVE BY APPROVED METHOD

OTHER COMMENTS