

CARLTON CONSERVATION STUDY BUILDING IDENTIFICATION FORM

NIGEL LEWIS AND ASSOCIATES
1984
Nigel Lewis Richard Aitken

BUILDING ADDRESS *90, 92, 94 CURTAIN ST*

BUILDING TITLE

TYPE
IF NOT RESIDENCE

EXISTING DESIGNATION

HBR No

AHC

GRADING

A B C D E F
No

STREETSCAPE

1 2 3

CONSERVATION AREA

SURVEY DATE

10/8/84

NEG FILE

B/32

TITLE

VOL FOL

STYLE

- Early Victorian
 Victorian
 Edwardian

CONSTRUCTION DATE

SOURCE

MATERIALS

WHERE NOT APPARENT



NOTABLE FEATURES/SIGNIFICANCE

CHIMNEY, 92

- | | | | | | |
|---------------------------------------------------------|---------------------------------------------------------|------------------------------------------------------------------------------------------------|---------------------------------------------------------|-------------------------------------------------------|-----------------------------------------------------------------|
| verandah decoration <input checked="" type="checkbox"/> | cast iron fence <input type="checkbox"/> | retains evidence of early colours or finishes <input type="checkbox"/> | intact shop front <input type="checkbox"/> | post supported shop verandah <input type="checkbox"/> | verandah roof and structure <input checked="" type="checkbox"/> |
| unpainted cement render <input type="checkbox"/> | unpainted decorative brickwork <input type="checkbox"/> | elaborate/high standard design of cement rendered surfaces <input checked="" type="checkbox"/> | fenestration intact <input checked="" type="checkbox"/> | | |

INTEGRITY

EXCELLENT GOOD FAIR POOR

Nos

ALTERATIONS AND RECOMMENDATIONS

NOS	SYMPATHETIC	RECS	INAPPROPRIATE	RECS	EXTREMELY INAPPROPRIATE	RECS
<i>92, 94</i>	<i>FENCES</i>	<i>-</i>	<i>+</i>			
<i>90</i>			<i>FENCE MISSING</i>	<i>S</i>		
			<i>BEAM DEMOLISHED</i>			
			<i>WINDOW MISSING</i>			

O = REINSTATE ORIGINAL DESIGN; S = REINSTATE SYMPATHETIC ALTERNATIVE; R = REMOVE; RAM = REMOVE BY APPROVED METHOD

OTHER COMMENTS