CARLTON CONSERVATION STUDY

NIGEL LEWIS AND ASSOCIATES 1984

BUILDING IDENTIFICATION FORM Nigel Lewis Richard Aitken
BUILDING ADDRESS 115, 117, 119 WETHIN ST
BUILDING TITLE TYPE IF NOT RESIDENCE
EXISTING DESIGNATION HBR NO AHC
GRADING A B C O D E F No
STREETSCAPE 1 2 2 3 CONSERVATION AREA
SURVEY DATE NEG FILE TITLE VOL FOL STYLE Parity Victorian Victorian Edwardian CONSTRUCTION DATE SOURCE MATERIALS WHERE NOT APPARENT
NOTABLE FEATURES/SIGNIFICANCE verandah roof and structure
verandah decoration fence fenestration intact post elaborate/high standard fence intact post fence fenestration fence fe
cement decorative of early colours shop supported design of cement render brickwork or finishes front shop verandah rendered surfaces
INTEGRITY EXCELLENT GOOD FAIR POOR Nos
ALTERATIONS AND RECOMMENDATIONS
NOS SYMPATHETIC RECS INAPPROPRIATE RECS EXTREMELY INNAPPROPRIATE RECS
117,119 FRUE VER-ROOF+ STO OLS
115 parce s.
THER COMMENTS