

CARLTON CONSERVATION STUDY BUILDING IDENTIFICATION FORM

NIGEL LEWIS AND ASSOCIATES
1984
Nigel Lewis Richard Aitken

BUILDING ADDRESS 917 DRUMMOND ST

BUILDING TITLE _____ TYPE _____
IF NOT RESIDENCE

EXISTING DESIGNATION HBR No _____ AHC _____

GRADING A B C D E F
No

STREETSCAPE 1 2 3 CONSERVATION AREA _____

SURVEY DATE 26/3/84
NEG FILE 62/6
TITLE _____
VOL _____ FOL _____
STYLE
 Early Victorian
 Victorian
 Edwardian
CONSTRUCTION DATE _____
SOURCE _____
MATERIALS
WHERE NOT APPARENT _____



NOTABLE FEATURES/SIGNIFICANCE

verandah decoration <input checked="" type="checkbox"/>	cast iron fence <input type="checkbox"/>	retains evidence of early colours or finishes <input type="checkbox"/>	intact shop front <input type="checkbox"/>	post supported shop verandah <input type="checkbox"/>	verandah roof and structure <input checked="" type="checkbox"/>	elaborate/high standard design of cement rendered surfaces <input checked="" type="checkbox"/>
unpainted cement render <input type="checkbox"/>	unpainted decorative brickwork <input type="checkbox"/>				fenestration intact <input checked="" type="checkbox"/>	

INTEGRITY EXCELLENT GOOD FAIR POOR
Nos _____

ALTERATIONS AND RECOMMENDATIONS

NOS	SYMPATHETIC	RECS	INAPPROPRIATE	RECS	EXTREMELY INAPPROPRIATE	RECS
			<u>fence</u>	<u>S</u>		

0 = REINSTATE ORIGINAL DESIGN; S = REINSTATE SYMPATHETIC ALTERNATIVE; R = REMOVE; RAM = REMOVE BY APPROVED METHOD

OTHER COMMENTS _____