

# CARLTON CONSERVATION STUDY BUILDING IDENTIFICATION FORM

NIGEL LEWIS AND ASSOCIATES  
1984  
Nigel Lewis Richard Aitken

BUILDING ADDRESS *PARK ST*

BUILDING TITLE *FORMER N-CARLTON STATION*

TYPE *RAILWAY STATION*  
IF NOT RESIDENCE

EXISTING DESIGNATION

HBR No

AHC

GRADING

A  B  C  D  E  F

No

STREETSCAPE

1  2  3

CONSERVATION AREA

SURVEY DATE *16/2/84*

NEG FILE *15/16*

TITLE

VOL FOL

STYLE

CONSTRUCTION DATE

SOURCE

MATERIALS

WHERE NOT APPARENT



NOTABLE FEATURES/SIGNIFICANCE

*PLATE*  
*C.I. VERANDAH + SPANDED ENDS.*  
*(See A. Ward's railway station study)*

unpainted  
cement  
render

unpainted  
decorative  
brickwork

retains evidence  
of early colours  
or finishes

intact  
shop  
front

post  
supported  
shop verandah

elaborate/high standard  
design of cement  
rendered surfaces

INTEGRITY

EXCELLENT  GOOD  FAIR  POOR

Nos

ALTERATIONS AND RECOMMENDATIONS

NOS	SYMPATHETIC	RECS	INNAPPROPRIATE	RECS	EXTREMELY INNAPPROPRIATE	RECS
					<i>PLATFORM REMOVED</i>	<i>S</i>
					<i>FENCING -</i>	
					<i>SHOULD BE RELOCATED</i>	

0 = REINSTATE ORIGINAL DESIGN; S = REINSTATE SYMPATHETIC ALTERNATIVE; R = REMOVE; RAM = REMOVE BY APPROVED METHOD

OTHER COMMENTS