

CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

LORRAINE HUDDLE 237619
 LOUISE HONMAN
 RICHARD AITKEN

1986

BUILDING ADDRESS *194-196 Autumn St*

Type *R* Original Use *R*

PRESENT BUILDING TITLE

EXISTING DESIGNATION & FILE No. HBR No. NER No. NTC FN. GRC No.

GRADING A B C D E S

STREETSCAPE LEVEL 1 2 3 CONSERVATION AREA

SURVEY DATE *30/4*

NEG. FILE *044-020*

PERIOD
 Early Victorian
 Victorian
 Late Victorian
 Edwardian
 Inter War
 Post War



MATERIALS
 walls *wb* roof *ci*

CONSTRUCTION DATE source

SIGNIFICANT FEATURES

original materials	<input checked="" type="checkbox"/>	early paint colour scheme or original unpainted finish	<input type="checkbox"/>	ornamental wall detailing	<input type="checkbox"/>
original doors, windows, hoods	<input checked="" type="checkbox"/>	intact verandah / porch structure	<input type="checkbox"/>	original parapet	<input type="checkbox"/>
original roof form and finish	<input checked="" type="checkbox"/>	original chimneys	<input checked="" type="checkbox"/>	eaves roof or gable decoration	<input checked="" type="checkbox"/>
intact verandah decoration	<input type="checkbox"/>	early fence	<input type="checkbox"/>	early garden	<input type="checkbox"/>
other prominent contributing elevations	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>

INTEGRITY RATING excellent good fair poor

ALTERATIONS & SPECIFIC GUIDELINES					
No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate
					<i>verandah</i>

o : reinstate original design r : remove
 s : reinstate sympathetic alternative ram: remove by approved method