

CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

LORRAINE HUDDLE 240230
LOUISE HONMAN
RICHARD AITKEN

1986

BUILDING ADDRESS 6 Thomas Street

Type Flat Original Use Res

PRESENT BUILDING TITLE "Dumbarton" formerly ELwood.

EXISTING DESIGNATION
& FILE No.HBR
No.NER
No.NTC
FN.GRC
No.

GRADING

A

B

C

D

E

S

STREETSCAPE LEVEL

1

2

3

CONSERVATION
AREA

SURVEY DATE

15-1-76

NEG. FILE

456-009
030

PERIOD

Early Victorian

Victorian

Late Victorian

Edwardian

Inter War

Post War

MATERIALS

walls

roof

ci



CONSTRUCTION DATE

1553

source

LH index Dumbarton HSE

SIGNIFICANT FEATURES

original materials

early paint colour scheme or original
unpainted finish

ornamental wall detailing

original doors, windows, hoods

intact verandah / porch structure

original parapet

original roof form and finish

original chimneys

eaves roof or gable
decoration

intact verandah decoration

early fence

early garden

other prominent contributing
elevations

INTEGRITY RATING

excellent

good

fair

poor

ALTERATIONS & SPECIFIC GUIDELINES

No.

Sympathetic

S.G.

Inappropriate

S.G.

Extremely Inappropriate

o : reinstate original design

r : remove

s : reinstate sympathetic alternative

ram: remove by approved method

CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

page 2

CITATION & HISTORY

Henry Roebuck's house (town premises)

Room extensions + shed 1935. Elder E Brown

Built not long before March 1853 (H. Elder Duranton HSE)

Appears on 1854 map.

Location. Sale 1870 - D. Duranton

Index p. 205.

Henry Roebuck G.A. 6.5.1919. d. on 15.2.1919.

Pioneer Index Roebuck.

Statement of Significance

REFERENCES

in Geelong No 54. p 10

Geelong Archives. Location maps of a 2 storey brick and iron house between Durham and Gertrude Streets.

Building Register, 1925.

Index p 54b. 205.

See Photo. card H. Elder for Roebuck house

described as a landmark in 1853.

Sources of early photographs