Address 1339 Murradoc Rd Site Name Primary School	St. Leonards 3223	Record No. 253 Page No. 1 of 4
Gey Original 1910 salbro-	Major Changes	Existing Use/Type
		P. School Precinct Name Survey Date 20/11/1995 Neg. No. 5/8 Video Track No.
	88087	Recorded By
Heritage Status:	Condition of the fabric:	Present Threats:
CATEGORY REGISTRATION NUMBER	Condition of the fabric: □ Excellent ⊠ Good	Present Threats: Human; mining Human; visitor erosion
CATEGORY REGISTRATION NUMBER National Estate:	Carte Carenteen Co. Care Co.	Human; mining
CATEGORY REGISTRATION NUMBER National Estate: Nominated	□ Excellent	☐ Human; mining ☐ Human; visitor erosion
CATEGORY REGISTRATION NUMBER National Estate: Nominated Registered .	□ Excellent ⊠ Good □ Fair □ Poor □ Ruinous □ Unexposed	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism
National Estate: Nominated Registered Historic Buildings Register	□ Excellent □ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site:	Human; mining Human; visitor erosion Human; vandalism Human; development
National Estate: Nominated Registered Historic Buildings Register Nominated	□ Excellent ⊠ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site: □ Excellent ⊠ Good	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☑ Human; conservation/maintenance
National Estate: Nominated Registered Historic Buildings Register Registered Registered Registered	□ Excellent □ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site:	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Natural Forces; vegetation
National Estate: Nominated Registered Historic Buildings Register Registered Registered Registered	□ Excellent □ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site: □ Excellent □ Good □ Fair □ Poor	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion
National Estate: Nominated Registered Historic Buildings Register Nominated Registered National Trust Register:	□ Excellent □ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site: □ Excellent □ Good □ Fair □ Poor □ Partially excavated □ Fully excavated	 ☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☑ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Natural Forces; vegetation
National Estate: Nominated Registered Historic Buildings Register Nominated Registered National Trust Register:	□ Excellent □ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site: □ Excellent □ Good □ Fair □ Poor □ Partially excavated □ Fully excavated	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Not threatened ☐ Not threatened ☐ Not threatened
National Estate: Nominated Registered Registere: Planning Scheme:	□ Excellent □ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site: □ Excellent □ Good □ Fair □ Poor □ Partially excavated □ Fully excavated Significant A	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☑ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Natural Forces; vegetation Not threatened Not
National Estate: Nominated Registered Registere: Planning Scheme:	□ Excellent □ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site: □ Excellent □ Good □ Fair □ Poor □ Partially excavated □ Fully excavated □ Significant A □ Original Materials □ Original Chimneys	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Not threatened ☐ Not threatened ☐ Original Roof ☐ form & finish ☐ Original Openings ☐ doors & windows
National Estate: Nominated Registered Registere: Planning Scheme: Archaeological Register:	□ Excellent □ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site: □ Excellent □ Good □ Fair □ Poor □ Partially excavated □ Fully excavated □ Significant A □ Original Materials □ Original Chimneys	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Not threatened ☐ Not threatened ☐ Original Roof form & finish ☐ Original Openings doors & windows ☐ Original Decoration gable
National Estate: Nominated Registered Registere: Planning Scheme: Archaeological Register:	□ Excellent □ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site: □ Excellent □ Good □ Fair □ Poor □ Partially excavated □ Fully excavated □ Significant A □ Original Materials □ Original Chimneys □ Wall Decoration	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Not threatened ☐ Not threatened ☐ Original Roof ☐ form & finish ☐ Original Openings ☐ doors & windows
CATEGORY REGISTRATION NUMBER National Estate:	□ Excellent □ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site: □ Excellent □ Good □ Fair □ Poor □ Partially excavated □ Fully excavated □ Significant A □ Original Materials □ Original Chimneys □ Wall Decoration □ Verandah Structure	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Not threatened ☐ Not threatened ☐ Noriginal Roof form & finish ☐ Original Openings doors & windows ☐ Original Finish funpainted ☐ Original Finish funpainted ☐ Original Finish funpainted ☐ Original Finish funpainted ☐ Original Pooresistory ☐ Human; vandalism ☐ Not threatened ☐ Vandalism ☐ Vandalism ☐ Human; vandalism ☐ Human; vandalism ☐ Human; vandalism ☐ Not threatened ☐ Vandalism ☐ Human; vandalism ☐ Human; vandalism ☐ Human; vandalism ☐ Human; vandalism ☐ Not threatened ☐ Vandalism ☐ Human; v

Site Plan/ Location Sketch Not To Scale Co-ordinates E 299700 N5772450	Site No. Street/Site name Murradoc Rd Murradoc Rd	Town / Sul	ards 3223	Record No. 253
Ownership: Cadastral Location: County Grant Parish Paywit Allotment Sec 1 Pt C/A 27C Block The complex of school buildings is sited on the corner of Murradoc Rd and Wattletree Ave, with mature cypress trees on the south boundary. The older school building is a freestanding single storey brick structure, with a steep pitch gable roof, running east-west, and clad in corrugated iron. The west elevation features two pairs of off-centre timber framed, multi-paned double hung windows with openable toplights. It has plain timber bargeboards on the gable end, with decorative timber strutwork and a louvered vent The south elevation has four timber framed, multi-paned, openable clerestorey windows under the eave line. The building appears relativley unaltered, with new spouting and downpipes, and	Site Plan/ Location Sketch	Not To Scale		ilian Map Grid
Ownership: Crown Private Resident owner Occupier only Local Govt Area County County Grant Paywit Allotment Sec 1 Pt C/A 27C Block Physical Description of Site: The complex of school buildings is sited on the corner of Murradoc Rd and Wattletree Ave, with mature cypress trees on the south boundary. The older school building is a freestanding single storey brick structure, with a steep pitch gable roof, running east-west, and clad in corrugated iron. The west elevation features two pairs of off-centre timber framed, multi-paned double hung windows with openable toplights. It has plain timber bargeboards on the gable end, with decorative timber strutwork and a louvered vent The south elevation has four timber framed, multi-paned, openable clerestorey windows under the eave line. The building appears relativley unaltered, with new spouting and downpipes, and	94/1100	North Point	Co-ord	Laboration and magnetic field
Map Scale 1: 20,000 Access Informants Map Scale 1: 20,000	TOTAL	con 🔵		E 299700 N 5772450
Informants Inf	₩ Z	NA CONTRACTOR OF THE PARTY OF T	Map	Melways map 241
Ownership: Cadastral Location: County Grant Parish Paywit Allotment Sec 1 Pt C/A 27C Block Physical Description of Site: The complex of school buildings is sited on the corner of Murradoc Rd and Wattletree Ave, with mature cypress trees on the south boundary. The older school building is a freestanding single storey brick structure, with a steep pitch gable roof, running east-west, and clad in corrugated iron. The west elevation features two pairs of off-centre timber framed, multi-paned double nung windows with openable toplights. It has plain timber bargeboards on the gable end, with decorative timber strutwork and a louvered vent The south elevation has four timber framed, multi-paned, openable clerestorey windows under the eave line. The building appears relativley unaltered, with new spouting and downpipes, and	OOONGARBA		Scale	1: 20,000
Ownership: Crown Private Resident owner Occupier only Local Govt City of Greater Geelong Area Physical Description of Site: The complex of school buildings is sited on the corner of Murradoc Rd and Wattletree Ave, with mature cypress trees on the south boundary. The older school building is a freestanding single storey brick structure, with a steep pitch gable roof, running east-west, and clad in corrugated iron. The west elevation features two pairs of off-centre timber framed, multi-paned double nung windows with openable toplights. It has plain timber bargeboards on the gable end, with decorative timber strutwork and a louvered vent The south elevation has four timber framed, multi-paned, openable clerestorey windows under the eave line. The building appears relativley unaltered, with new spouting and downpipes, and	SPATON ST TE C EN	Architecture of the second	Access	
Ownership: Cadastral Location:	NOS SOLO SE RO SE	CODE OF STREET		
County Grant Resident owner Occupier only Parish Paywit	CENTRE OU BE ST. LEONARD ST. L	Reserve Camping Acad A	Informa	ants
Resident owner Occupier only Local Govt City of Greater Geelong Area Physical Description of Site: The complex of school buildings is sited on the corner of Murradoc Rd and Wattletree Ave, with mature cypress trees on the south boundary. The older school building is a freestanding single storey brick structure, with a steep pitch gable roof, running east-west, and clad in corrugated iron. The west elevation features two pairs of off-centre timber framed, multi-paned double nung windows with openable toplights. It has plain timber bargeboards on the gable end, with decorative timber strutwork and a louvered vent The south elevation has four timber framed, multi-paned, openable clerestorey windows under the eave line. The building appears relativley unaltered, with new spouting and downpipes, and	Ownership:	Ca	dastral	Location:
Allotment Sec 1 Pt C/A 27C Block Physical Description of Site: The complex of school buildings is sited on the corner of Murradoc Rd and Wattletree Ave, with mature cypress trees on the south boundary. The older school building is a freestanding single storey brick structure, with a steep pitch gable roof, running east-west, and clad in corrugated iron. The west elevation features two pairs of off-centre timber framed, multi-paned double nung windows with openable toplights. It has plain timber bargeboards on the gable end, with decorative timber strutwork and a louvered vent The south elevation has four timber framed, multi-paned, openable clerestorey windows under the eave line. The building appears relativley unaltered, with new spouting and downpipes, and	☑ Crown ☐ Private	County	Grant	
Govt Area City of Greater Geelong Physical Description of Site: The complex of school buildings is sited on the corner of Murradoc Rd and Wattletree Ave, with mature cypress trees on the south boundary. The older school building is a freestanding single storey brick structure, with a steep pitch gable roof, running east-west, and clad in corrugated iron. The west elevation features two pairs of off-centre timber framed, multi-paned double hung windows with openable toplights. It has plain timber bargeboards on the gable end, with decorative timber strutwork and a louvered vent The south elevation has four timber framed, multi-paned, openable clerestorey windows under the eave line. The building appears relativley unaltered, with new spouting and downpipes, and	Resident owner Occupier only	Parish [Paywit	nernage Status
Physical Description of Site: The complex of school buildings is sited on the corner of Murradoc Rd and Wattletree Ave, with mature cypress trees on the south boundary. The older school building is a freestanding single storey brick structure, with a steep pitch gable roof, running east-west, and clad in corrugated iron. The west elevation features two pairs of off-centre timber framed, multi-paned double nung windows with openable toplights. It has plain timber bargeboards on the gable end, with decorative timber strutwork and a louvered vent The south elevation has four timber framed, multi-paned, openable clerestorey windows under the eave line. The building appears relativley unaltered, with new spouting and downpipes, and	Local Control of the	Allotment	Sec 1 Pt	t C/A 27C
The complex of school buildings is sited on the corner of Murradoc Rd and Wattletree Ave, with mature cypress trees on the south boundary. The older school building is a freestanding single storey brick structure, with a steep pitch gable roof, running east-west, and clad in corrugated iron. The west elevation features two pairs of off-centre timber framed, multi-paned double nung windows with openable toplights. It has plain timber bargeboards on the gable end, with decorative timber strutwork and a louvered vent The south elevation has four timber framed, multi-paned, openable clerestorey windows under the eave line. The building appears relativley unaltered, with new spouting and downpipes, and		Block [betering
Ave, with mature cypress trees on the south boundary. The older school building is a freestanding single storey brick structure, with a steep pitch gable roof, running east-west, and clad in corrugated iron. The west elevation features two pairs of off-centre timber framed, multi-paned double nung windows with openable toplights. It has plain timber bargeboards on the gable end, with decorative timber strutwork and a louvered vent The south elevation has four timber framed, multi-paned, openable clerestorey windows under the eave line. The building appears relativley unaltered, with new spouting and downpipes, and	Physical Description of Site:			touting
along has a second as parts	Ave, with mature cypress trees on the south The older school building is a freestanding gable roof, running east-west, and clad in a The west elevation features two pairs of off hung windows with openable toplights. It havith decorative timber strutwork and a louve The south elevation has four timber framed under the eave line. The building appears relativley unaltered, we have the south elevation has four timber framed and the eave line.	n boundary. single storey becorrugated iron. centre timber tas plain timber ered vent d, multi-paned, with new spouti	rick struc framed, r bargebo openable	cture, with a steep pitch multi-paned double ards on the gable end, e clerestorey windows
	or agated metal clauding of	i tile 1001.		

Interest Groups:

Site No.	Street/Site name Murradoc Rd		Town / Suburb St. Leonards 3223	Record No. 253 Page No. 3 of 4
Types of Site) \$:			Statement of Cur.
monument	⊠ public	maritime	tree(s)	machinery
☐ industrial	□ commercial	relic/ruin	garden	□ building
agricultural	residential residential	fence	□ landscape	miscellaneous
☐ recreational	infrastructure	gate	Religious	That been the only local Γ
Historical Th	iemes:	guideal accestacies To estaga edit berina	a) komunia kuto ila pada Mangana ta	opened in 1674 oc. od en P aywit Nort h - The breach
Early Settleme	ent		Communities	cmEducation
Maritime			Landscapes	a laterio da del le mi
Tourism			The Wider World	noin knomboa
Workforce			Cultural Activity	
Townships			Miscellaneous	
Portarlington. This new brick	school was open f (2) k school was open ebrations for the sc	ed in Novembe	er 1910.(3) The lo	was located closer to
2. ibid p. 1022	3) Vision and Realisation Balla-wein a history of the pers. comm.	•	<i>rine</i> , p.116	

Site	No. Street/Site name	200 (11W0)	Town / Suburb	Record No. 253
Address	1339 Murradoc Rd		St. Leonards 3223	Page No.
Statement	of Cultural Sig	ınifi sanası		4 of 4
			style of brick construction	on and has remained
relatively una	Itered. It is now located	within a complex of s	chool buildings.	Ishteubni []
St Leonards F	Primary School is of soc	cial and historic value to	the local St Leonard's c	
Primary Schoopened in 18	ool of 1910 is the secon 74 served the small an . The brick building of 1	d school on this site. T d modest farming and	nards community for over The earlier weatherboard fishing communities at S nore established nature	one-room building It Leonards, Murradoc and of St Leonards after the
	odenisbama) - 350			
It is of LOCA	L cultural significance.	genebas l		Maritime
Addition	al Information	The Wider		Tourism
				Workforce
				Townships
				History of
				Early educat
		n afgeden zoek filler Gebeure		individuals unit for the comp
	nega kanaka danga sa Manggarapan danga sa Manggarapan danga sa			St. Leonards building on le large and thi Portarlington
bud garg	্রালুক্তর isoM প্রবিধি	(2 1.01 81 ison) - 1 40 cs 21 -		This new bri centenary ce