BELLARINE HERITAGE STUDY RECORD SHEET

Site No. Street/Site Name Address 13 Princess St	Town / Suburb Posto Drysdale 3222	Record No. 75
ey original and original	Major Changes	Existing Use/Type hall Precinct Name Survey Date
ANALYSIS TO ANALYS	RSL	Neg. No. 7/24 Video Track No. Recorded By RL/KF
Heritage Status: CATEGORY REGISTRATION NUMBER National Estate:	Condition of the fabric: □ Excellent □ Good □ Fair □ Poor	Present Threats: Human; mining Human; visitor erosion
Nominated	☐ Ruinous ☐ Unexposed	☐ Human; vandalism
Historic Buildings Register Nominated Registered Registere:	Integrity of the site: Excellent Good Fair Poor Partially excavated Fully excavated	☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Natural Forces; vegetation ☐ Not threatened
Planning Scheme:	Significant A	Architectural Features:
Historical Archaeological Register :	☑ Original Materials☐ Original Chimneys	Original Roof form Original Openings doors & windows
Other:	☐ Wall Decoration	Original Pinish Description

BELLARINE HERITAGE STUDY RECORD SHEET

Site No. Street/Site name	Town / Su	I Record No.
Address 13 Princess St	Drysdale	Page No. 2 of 4
Site Plan/ Location Sketch	Not To Scale	Australian Map Grid Co-ordinates
Sunday Sunday Merical Area Sunday Merica	North Point North	Map Scale Access Informants
Ownership:	1 _	adastral Location:
☐ Crown ☐ Private	County	Grant
Resident owner Occupier only	Parish	Bellarine
Local Local Local	Allotment [171072
Govt City of Greater Geelong Area	Block [belsage
Physical Description of Site:		Dataian
A simple single gable corrugated iron rarched double hung windows and a sm	roof brick building v nall entry porch.	with plain bargeboards, slightly
		A leabate
		glator :
Veg nat Decoration		
Relevant Special Interest Groups:	in de la Rechetei Ingo en reche	