Site No. Street/Site Name Address 39 Wyndham St	Town / Suburb Postco	Record No. 89
Site Name St. Thomas' Catholic Chu	ırch	Page No. 1 of 4
Cey Original C 1855	Major Changes	Existing Use/Type church
223		Precinct Name Survey Date 22/12/1995
		Neg. No. 10/4,5,7 Video Track No. Recorded By
noi Lycation	anneO	RL/KF
Heritage Status: CATEGORY REGISTRATION	Condition of the fabric:	Present Threats:
CATEGORY REGISTRATION NUMBER National Estate:	Condition of the fabric: ☑ Excellent ☐ Good ☐ Fair ☐ Poor	The second secon
CATEGORY REGISTRATION NUMBER	⊠ Excellent □ Good	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development
CATEGORY REGISTRATION NUMBER National Estate: Nominated Registered	☐ Excellent ☐ Good ☐ Fair ☐ Poor ☐ Ruinous ☐ Unexposed ☐ Integrity of the site:	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development
National Estate: Nominated Registered Historic Buildings Register Nominated Home Register	⊠ Excellent □ Good □ Fair □ Poor □ Ruinous □ Unexposed Integrity of the site: □ Excellent □ Good □ Fair □ Poor	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion
National Estate: Nominated Registered Historic Buildings Register Nominated Registered Registered	☐ Excellent ☐ Good ☐ Fair ☐ Poor ☐ Ruinous ☐ Unexposed ☐ Integrity of the site: ☐ Excellent ☐ Good	Human; mining Human; visitor erosion Human; vandalism Human; development Human; conservation/maintenance Human; stock
National Estate: Nominated Registered Historic Buildings Register Nominated Registered National Trust Register:	Excellent Good Fair Poor Integrity of the site: Excellent Good Partially excavated Fully excavated	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Natural Forces; vegetation
National Estate: Nominated Registered Historic Buildings Register Nominated Registered National Trust Register: Planning Scheme:	Excellent Good Fair Poor Integrity of the site: Excellent Good Partially excavated Fully excavated	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Natural Forces; vegetation ☐ Not threatened
National Estate: Nominated Registered Historic Buildings Register Nominated Registered National Trust Register: Planning Scheme: Historical Archaeological Register:	Excellent Good Pair Poor Integrity of the site: Excellent Good Partially excavated Fully excavated Significant Ar Original Materials Original Chimneys	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Natural Forces; vegetation ☒ Not threatened Image: Angle of the control of t
National Estate: Nominated Registered Historic Buildings Register Nominated Registered National Trust Register: Planning Scheme: Historical Archaeological Register:	Excellent Good Fair Poor Integrity of the site: Excellent Good Fair Poor Partially excavated Fully excavated Significant A Original Materials Original Chimneys Wall Decoration Original Chimneys Original Chimneys	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Natural Forces; vegetation ☐ Not threatened Image: Annual Forces of the control of the cont
National Estate: Nominated Registered Historic Buildings Register Nominated Registered National Trust Register: Planning Scheme: Historical Archaeological Register:	Excellent Good Fair Poor Integrity of the site: Excellent Good Fair Poor Partially excavated Fully excavated Significant A Original Materials Original Chimneys Wall Decoration Wall Decoration Poor Wall Decoration Wall Decorat	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Natural Forces; vegetation ☒ Not threatened rchitectural Features: Original Roof [form & finish] Original Openings [doors & windows]
National Estate: Nominated Registered Register: Planning Scheme: Historical Archaeological Register:	Excellent Good Fair Poor Integrity of the site: Excellent Good Fair Poor Partially excavated Fully excavated Fully excavated Good Fair Poor Partially excavated Fully excavated Good Fully excavated Good Fully excavated Good Partially excavated Good Good Partially excavated Good Goo	☐ Human; mining ☐ Human; visitor erosion ☐ Human; vandalism ☐ Human; development ☐ Human; conservation/maintenance ☐ Human; stock ☐ Natural Forces; erosion ☐ Natural Forces; vegetation ☐ Not threatened Image: Annual Forces of the control of the cont

Site Address No. Street/Site name 10001009 1998 1998 Wyndham St	Town / Subi	the same of the sa	Record No. 89 Page No. 2 of 4
Springs AUA Springs FLINDERS VIEW Secondary Secondary Secondary WYNDHAM WYNDHAM Sunday Sunday Method Area Sunday Method Area Sunday Method Area Method Area Repair Rep	Scale Iorth Point MCKENZI Station Station Station Terminus Bush Warner Centre Bush Warner Centre Community Health	Co-ordina E 28 Map Melv	Map Grid ates 86850 N 5772030 ways map 238
RAILINATO OF PORTABLING TON:20 HIGH TO BEING STATION ST. MEWCOMBE.	DRYSDALE 3222 WOODVILLE	Informants	
Ownership:		dastral Lo irant	ocation:
of the tabelet Present Threats:		ellarine	refinge State
Govt City of Greater Geelong	Nock	ec 2, C/A's 6	5, Pt 7, 7A

Physical Description of Site:

St Thomas' is situated on a large block, with a wire fence on the Wyndham St boundary, and accessed through a iron gate with the rising sun motif. The light green painted brick building has a steep pitch gable roof, clad in slate, with triangular roof ventilators, and parapet gable ends.

The east elevation has five rectangular windows, with timber pointed arch motif fenestration, and quoinwork picked out in dark green paint. The building has buttresses, the corner one angled, and a bluestone plinth. The east elevation has a small gabled slate clad roof porch, with angled buttresses, a single window, a north facing door, and a cross at the apex of the gable parapet.

The north elevation has a large gabled entrance porch with across at the apex. It features a pointed arch motif window, a slate clad roof, and double timber doors facing east. The north elevation shows the main gable roof parapet, with a cross at the apex, and a small wall louvered vent as gable decoration.

Relevant Special Interest Groups:

aaress	ite No. Street/Site name Wyndham St		Town / Suburb Drysdale 3222	Record No. 89	
ddress				of 3 of dress	
ypes of Sites:	a. Server og magnegarenske skriv eksperioreren i i	Company of the Compan	e sa marana an an di Sarana (ilina di Sarana a	atement of cuts	
monument public		☐ maritime	☐ tree(s)	machinery	
industrial c	ommercial	☐ relic/ruin	garden	building building building building	
agricultural re	esidential	fence	□ landscape	miscellaneous	
recreational in	frastructure	gate	⊠ Religious	Thermas Calmond Silved Section (Calmond	
listorical Themes					
Early Settlement	•	· · · · · · · · · · · · · · · · · · ·	Communities	s of LOCAL estimate Lagranidaen	
Maritime			Landscapes	cmChurches	
Tourism	The second secon		The Wider World		
Workforce			Cultural Activity	maini isaciibb	
Townships			Miscellaneous		
Townships			Wiscenaneous		
as St. Thomas's and the					
In 1873 tenders were cavestry and in 1878 a 143 The two acre site has he	B pound bell was	s installed in time	for Christmas services.	4)	
In 1873 tenders were ca vestry and in 1878 a 143	B pound bell was	s installed in time	for Christmas services.	4)	

Site	No.	No. Street/Site name Town / Suburb Record No.				
Address	39	Wyndham S		Drysdale 3222	Page No.	8 9 4 of 4
Statomon	t of	Cultural	Significance:			Types
St Thomas' Cath Dowden and bu	nolic Chu ilt by Sim	rch building was mie and McLach	opened in 1856 when it h	oused the Church and St Joseph's Sch de in 1873 and the bell installed in 1878. uilding with quoinwork, buttresses and	The place has contained	a Hall and a
St Thomas' Cat	holic Chu	urch has aestheti	c, historic and social valu	e to the Drysdale district.		ohos [1]
with the Catholic over many years	commu s since th	nity in the Drysda	ale district continuously sir substantial church building	and the interesting details give it good nce 1856. It is part of a group of religiou of for the Bellarine Peninsula, and indicat	us buildings that have bee	en developed
It is of LOCAL	-		%			Histor
		ud Ormi				Early
						Maritir
						elisof
Addition	ial li	nformati	on			
						Towns
						Histor
						Catholi
						years in describ builden granite
						The op membe as St. 1
						In 1870 Vestry a
						The two
			•			