NEWTOWN URBAN CONSERVATION STUDY. - 'C' CITATIONS. Richard Peterson Architect & Conservation Consultant. Daniel Catrice Historian 1996.

NAME:

ADDRESS: 18 Buckland Avenue.

USE: House.

CONSTRUCTION DATE: 1925

SOURCE: Visual & 1

DESIGNER:

BUILDER:

CRITERIA:

H1; Ar1.

HISTORIC THEME: 2.3

DESCRIPTION: STYLE: Bungalow STORIES:

2 DETACHED.

MATERIALS: WALLS Timber

ROOF Iron

STRUCTURE Stud.

CONDITION: Very good INTACTNESS: Reasonable. THREATS: Damp.

SIGNIFICANT INTACT ELEMENTS:

FORM. VERANDAH. ROOF FORM. WINDOWS. CONTEXT Nos. 20 & 18.

SIGNIFICANCE:

TYPE: HISTORICAL. ARCHITECTURAL.

LEVEL: LOCAL.

DESIGNATION EXISTING: PLANNING SCHEME.


RECOMMENDED CONTROL: PLANNING SCHEME.


GRID REF:


SURVEY: RP DATE: 27.1.96

NEGS: 2.27 & 28

(Obscured).







NEWTOWN URBAN CONSERVATION STUDY - 'C' CITATION
Richard Peterson Architect & Conservation Consultant. Daniel Catrice Historian 1996.

HISTORY: George Brownhill purchased this block of land in 1924. A two-storey timber bungalow was built for Brownhill in 1925.

VISUAL DESCRIPTION: A large plain timber Bungalow, with a gable roof facing. Windows have 4 to 6 panes in the upper sash. There is a central gable-roof facing, as a porch, with a red brick balustrade and piers. Its gable has shingles and jettys on joists. Purlins are supported on timber barges.

SIGNIFICANCE: A large plain timber Californian Bungalow built in 1925. It is architecturally significant locally as characteristic of this style and historically significant as physical evidence of life in 1920s Newtown.

INTACTNESS: Apparently reasonable.

CONDITION: Very good, except rising damp in the brackets. It has caused longstanding structural problems and erosion of mortar.

¹ City of Newtown and Chilwell Ratebooks.