

WARRANTYTE DAIRY

Place No. 19

ADDRESS Yarra Street
Warrandyte

Last Update 12/03/2005

DESCRIPTION The ruins of the Warrandyte Dairy comprise the walls of the former coolroom, constructed of concrete block. The roof has gone along with the windows and doors. In 2005, the site was secured by chain mesh fencing to prevent public access.

The house on this site, now demolished, had a timber frame with cement sheet cladding and a corrugated cement sheet roof.

Condition Deteriorated **Integrity** Demolished - part

Threats Deterioration **Key elements** Ruins/remnants

Designer

HISTORY

Creation Date

Change Dates

Associations

Local Themes

6.04 - Local commerce & industry

STATEMENT OF SIGNIFICANCE Of local interest as an element remaining that demonstrates Warrandyte's former isolation despite its closeness to Melbourne.

LEVEL

RECOMMENDATIONS

Heritage Register Listings

Register	Reference	Zoning	Status
----------	-----------	--------	--------

None Specified

Extent

Heritage Schedule

External Paint Controls: On VHR: VHR Ref No:

Internal Alteration Controls: Prohibited Uses:

Tree Controls: Aboriginal Heritage Place:

Outbuildings or Fences: Incorporated Plan: Incorporated Plan Details

Description:

Conservation Management

Extra Research

BIBLIOGRAPHY Context Pty Ltd, (1991), City of Doncaster & Templestowe Heritage Study, City of Doncaster & Templestowe, Doncaster