PLACE IDENTIFICATION FORM

ADDRESS	TYPE
31 Harcourt Street	<pre>[X] Single Residence [] Multiple Unit Res. [] Shop [] Outbuildings [] Office [] Industrial Building [] Landscape feature [] Public building [] View [] Other</pre>
EXISTING DESIGNATION	HBR [] GBR [] AHC [] NT [] VAS []
STREETSCAPE LEVEL	1 [] 2 [X] 3 [] SIGNIFICANT [] STREET TREES KERB & GUTTERS Provisional Concealed by Fence **
GRADING	A[] B[X] C[] D[] E[] KEYNOTE BUILDING[]
RECOMMENDED FOR	Provisional HBR/GBR [] AHC [] URBAN CONSERVATION AREA [×] VAS [] PLANNING SCHEME PROTECTION [×] CULTURAL LANDSCAPE [] OTHER []
SURVEY DATE NOV 91. NEG FILE Title vol. Fol.	
THEME [] Early Settlement [] Mansions [X] Victorian Garden Suburb [] Municipal dev. [] 1870s growth [] Garden villas [] Working enclaves [] Commercial Centres [] Edwardian Prosperity [] Interwar Housing [] Flats and Offices	Concealed by fence
CONSTRUCTION DETAILS Date Architect Builder Elements	
[] Contributing garden [] Landmark tree	[] Original or early hard landscape layout [] Original or early fence
NOTABLE FEATURES/SIGNIFICANCE	
Grading to be determ	nined after site inspection
INTEGRITY Good [] Fair [] Poor [] UNKNOWN CROSS REFERENCED INFORMATION Associated significant garden	CONDITION Good [] Fair [] Poor [] UNENDWN

The site information given above has been determined from external street level inspection.

* On site inspection required.

PLACE IDENTIFICATION FORM - PRIVATE GARDENS ADDRESS 31 Harcourt Street TYPE Hawthorn [] Suburban Garden [] Cottage Garden [] Terrace House Garden [] View [] Villa Garden [] Landmark [] Other TITLE [X] City Mansion Garden EXISTING DESIGNATION HBR [] AHC [] NT [] SIGN. T. [] VGS [] STREETSCAPE LEVEL 1 [1 2 [X] 3 [] C [] D[X]B [] GRADING RECOMMENDED FOR [] AHC [] SIGNIFICANT TREE REG. [] PSP [CULTURAL LANDSCAPE [] URBAN CONSERVATION AREA [X] SURVEY DATE Nov. 91 NEG FILE Title Vol. Fol. THEME Early Settlement [X] Mansions [] Victorian Garden Suburb [] Municipal dev. 1870s growth 1 Garden villas Working enclaves 1 Commercial Centres [] Edwardian Prosperity Interwar Housing [] Flats and Offices DETAILS Date Designer Layout/Structures Garden not visible. Large Cedrus sp. showing over fence. NOTABLE FEATURES/SIGNIFICANCE Further investigation required. CONDITION Good [] INTEGRITY Good [] Fair [X] Fair [] Poor [] Poor [] Unclear ALTERATIONS

CROSS REFERENCED INFORMATION Associated Structures [X]

As the gardens were only surveyed from the front footpath, all assessments are incomplete and hence provisional. The scope of the study did not permit garden access which would be a pre-requisite for a more complete assessment.