

PLACE IDENTIFICATION FORM

ADDRESS

647 Burke Road

TYPE

- Single Residence
- Shop
- Office
- Landscape feature
- View
- Multiple Unit Res.
- Outbuildings
- Industrial Building
- Public building
- Other

TITLE

EXISTING DESIGNATION

HBR [] GBR [] AHC [] NT [] VAS []

STREETSCAPE LEVEL

1 [] 2 [x] 3 []
 SIGNIFICANT [] SIGNIFICANT []
 STREET TREES KERB & GUTTERS

GRADING

A [] B [] C [x] D [] E []
 KEYNOTE BUILDING []

RECOMMENDED FOR

HBR/GBR [] AHC [] URBAN CONSERVATION AREA [x]
 VAS [] PLANNING SCHEME PROTECTION [x]
 CULTURAL LANDSCAPE [] OTHER []

SURVEY DATE Nov .91.

NEG FILE 46-13.

Title
 Vol.
 Fol.

THEME

- Early Settlement
- Mansions
- Victorian Garden Suburb
- Municipal dev.
- 1870s growth
- Garden villas
- Working enclaves
- Commercial Centres
- Edwardian Prosperity
- Interwar Housing
- Flats and Offices

CONSTRUCTION DETAILS

Date c1874.?

Architect
 Builder
 Elements



- Contributing garden
- Landmark tree
- Original or early hard landscape layout
- Original or early fence

Magnolia Grandiflora

NOTABLE FEATURES/SIGNIFICANCE

INTEGRITY ? Good [] CONDITION ? Good []
 Fair [] Fair []
 Poor [] Poor []

CROSS REFERENCED INFORMATION

Associated significant garden [x]

PLACE IDENTIFICATION FORM - PRIVATE GARDENS

ADDRESS 647 Burke Road
Hawthorn

TYPE

Cottage Garden Suburban Garden
 Terrace House Garden View
 Villa Garden Landmark
 City Mansion Garden Other

TITLE

EXISTING DESIGNATION

HBR AHC NT SIGN. T. VGS

STREETSCAPE LEVEL

1 2 3

GRADING

A B C D E

RECOMMENDED FOR

HBR AHC SIGNIFICANT TREE REG. PSP
CULTURAL LANDSCAPE URBAN CONSERVATION AREA

SURVEY DATE 28.11.91

NEG FILE EA2/12

Title
Vol.
Fol.

THEME

- Early Settlement
 Mansions
 Victorian Garden Suburb
 Municipal dev.
 1870s growth
 Garden villas
 Working enclaves
 Commercial Centres
 Edwardian Prosperity
 Interwar Housing
 Flats and Offices

DETAILS

Date

Designer

Layout/Structures

Original fence and gates missing. Later cyclone fence with overgrown Coprosma hedge.
 Entrance and driveway on northern side of property, driveway sweeping round to the front door. Huge tree in front lawn, possibly Lillypilly?

NOTABLE FEATURES/SIGNIFICANCE

Further investigation required.

INTEGRITY Good
 Fair
 Poor

CONDITION Good
 Fair
 Poor

ALTERATIONS

CROSS REFERENCED INFORMATION

Associated Structures

As the gardens were only surveyed from the front footpath, all assessments are incomplete and hence provisional. The scope of the study did not permit garden access which would be a pre-requisite for a more complete assessment.

