

## PLACE IDENTIFICATION FORM

## ADDRESS

18/20 Riversdale Road

## TYPE

- |  |  |
|--|--|
| <input type="checkbox"/> Single Residence  | <input checked="" type="checkbox"/> Multiple Unit Res. |
| <input type="checkbox"/> Shop              | <input type="checkbox"/> Outbuildings                  |
| <input type="checkbox"/> Office            | <input type="checkbox"/> Industrial Building           |
| <input type="checkbox"/> Landscape feature | <input type="checkbox"/> Public building               |
| <input type="checkbox"/> View              | <input type="checkbox"/> Other                         |

## TITLE

"Loloma" and "Linden"

## EXISTING DESIGNATION

HBR ☐ GBR ☐ AHC ☐ NT ☐ VAS ☐

## STREETSCAPE LEVEL

1 ☐ 2 ☒ 3 ☐  
 SIGNIFICANT ☐ SIGNIFICANT ☐  
 STREET TREES KERB & GUTTERS

## GRADING

A ☐ B ☐ C ☒ D ☐ E ☐  
 KEYNOTE BUILDING ☐

## RECOMMENDED FOR

HBR/GBR ☐ AHC ☐ URBAN CONSERVATION AREA ☒  
 VAS ☐ PLANNING SCHEME PROTECTION ☒  
 CULTURAL LANDSCAPE ☐ OTHER ☐

SURVEY DATE Nov. 91.

NEG FILE 35.11.

Title

Vol.

Fol.

## THEME

- ☐ Early Settlement  
☐ Mansions  
☒ Victorian Garden Suburb  
☐ Municipal dev.  
☐ 1870s growth  
☐ Garden villas  
☐ Working enclaves  
☐ Commercial Centres  
☐ Edwardian Prosperity  
☒ Interwar Housing  
☒ Flats and Offices

## CONSTRUCTION DETAILS

Date

Architect

Builder

Elements



- |  |  |
|--|--|
| <input type="checkbox"/> Contributing garden | <input type="checkbox"/> Original or early hard landscape layout |
| <input type="checkbox"/> Landmark tree       | <input checked="" type="checkbox"/> Original or early fence      |

## NOTABLE FEATURES/SIGNIFICANCE

INTEGRITY Good ☒  
 Fair ☐  
 Poor ☐

CONDITION Good ☒  
 Fair ☐  
 Poor ☐

## CROSS REFERENCED INFORMATION

Associated significant garden ☐