NEWTOWN URBAN CONSERVATION STUDY. - 'C' CITATIONS. Ref: 48

Richard Peterson Architect & Conservation Consultant. Daniel Catrice Historian 1996.

NAME:

ADDRESS: 17 Buckland Avenue.

USE: House.

CONSTRUCTION DATE: 1923

SOURCE: Visual & 1

DESIGNER:

BUILDER:

CRITERIA: H1; Ar1

HISTORIC THEME: 2.3

DESCRIPTION: STYLE: Bungalow STORIES: 1 DETACHED.

MATERIALS: WALLS Timber

ROOF Iron

STRUCTURE Stud.

CONDITION: Very good

INTACTNESS: Very good.

THREATS: -

SIGNIFICANT INTACT ELEMENTS:

FORM. VERANDAH. ROOF FORM. GABLE DECORATION. VERANDAH DECORATION.

CHIMNEY. WINDOWS. CONTEXT Nos. 13, 15, 17A, etc.

SIGNIFICANCE:

TYPE: HISTORICAL. ARCHITECTURAL.

LEVEL: LOCAL.

DESIGNATION EXISTING: PLANNING SCHEME.

RECOMMENDED CONTROL: PLANNING SCHEME.


GRID REF:

SURVEY: RP

DATE:

27.1.96

NEGS: 2.25



HISTORY: This house was erected in 1923 for Florence Mann.

VISUAL DESCRIPTION: A simple, double-fronted timber Californian Bungalow, with a broad gable across. A major gable projects forward at right and minor gables at left, over the verandah. These jetty on joists, with rectangular louvred vents. The verandah has decorative fretwork brackets, on post-piers over. There is a canted bay window.

SIGNIFICANCE: A timber Californian Bungalow built in 1923. It is architecturally significant as characteristic of this style and historically significant as the representative embodiment of life in 1920s Newtown.

INTACTNESS: Very good. The high timber fence is not appropriate.

CONDITION: Very good.

ONDERNIED CONTROL

ORGE SURVEY: RP

¹ City of Newtown and Chilwell Ratebooks.